

Exhibit 29

From: Hossein Ruhi
To: Christopher Toth; Earl Lokers; Jose Navarro; Mak Daoud; Rob Hawk; Robert Ferrier
Date: Friday, July 27, 2007 10:37:34 AM
Subject: Re: Fwd: 5700 Block of Soledad Mt. Road - Concerns of Citizens

With this email I am asking that our lab do an exploratory coring to see if there is void under the pavement or not. If there is no void then we should prob thru the hole to see if the soil is loose or not. if it is loose then we need to do a n appropriate repair otherwise just overlay the sunken areas.

>>> Robert Ferrier 07/27/2007 10:19 AM >>>

Chris,

Sounds good.

What's the next step re the subsidence?

RJF

>>> Christopher Toth 7/27/2007 9:07 AM >>>

the sewer mains in this area are reported to be in good shape and not structurally impacted by soil movement. Chris

Exhibit 30

From: Rob Hawk
To: tac@san.rr.com
Date: Fri, Aug 3, 2007 10:21 AM
Subject: Re: Street Water Leak/5700 block of Soledad Mtn.

Mr. Crabbe: Thank you for the photos. I recall our conversation yesterday regarding an SDG&E Crew that you said detected gas near the repair area; I don't recall you mentioning the water leak. I will pass these along to the Water Department along with a "heads up" about the apparent gas leak, and to our lab.

Thank you.

Rob Hawk

Robert N. Hawk, PE
Senior Engineering Geologist/Deputy City Engineer
City of San Diego, Engineering and Capital Projects
Field Engineering Division, MS 18
9485 Aero Drive San Diego, CA 92123
(858) 573-5011
(858) 627-3297 (Fax)
rhawk@san-diego.gov

Working Together to Engineer a Better Tomorrow

>>> <tac@san.rr.com> 8/3/07 10:04 AM >>>
Mr. Hawk,

I contacted you yesterday concerning the water main break on the 5700 block of Soledad Mtn. Rd. in La Jolla. The repair area has been leaking for two days. I alerted the city water yesterday and it still leaks water. In our conversation yesterday you asked for pictures. These two will show you new leaks after the fixed water main. Our main concern is stopping anymore damage to the street, and any damage to surrounding areas. Thank you for your help.

regards, Tom

Crabbe

CC: Adamos, Ralph; Daoud, Mak; Lokers, Earl; Ruhi, Hossein; Ruiz, Alex; Toth, Christopher





Exhibit 31

Sewer/Water Infrastructure Management

Actions



Work Order Data Entry

SR#: 3001954	Wo#: 1	Priority: 1	Radio #: 1933	Wtr/Swr: W	WO Stat: CMP	WO Recd Dt:	Orig Prob Cd: 1161
Prob Cd / Primary Ind: 1022N Y							Field Bk Pg/Grid: C12S
Street #	Frac	Dir	Street Name	Sfx	Suite#	Juris	Data Steward: 1970 MICHAEL BASOM
5715			SOLEDAD MTN	RD		SD	X St: DESERT VIEW
Inter:							Thomas Bros Pg: 1248A2
Loc Desc: WTR LEAKING UP OUT OF PATCH FROM REP SR#2999660							Service Area: 2
Job Desc:							ES Service Area: W
Special Inst:							Plant Service Area: MI
							Assign Dt: 08/02/07 11:40
							WO Gen Dt: 08/02/07 11:37

USA#:	Exp Dt:	Fac Typ:	Fac Seq#:	Request: TOM	Pl#: 619	997-4369
-------	---------	----------	-----------	--------------	----------	----------

Work Cd	Action Cd	Service Request Comments				
ESINV	INV					
ST: 08/02/07 13:00	End: 08/02/07 13:15	JO #:	53546	Emp: 1	Hrs: 0.30	

WO Comments: Page 2 of 2	11-11 NO 1161 FOUND
Creation Dt/Tm: 08/02/07 11:37	
Upd Dt/Tm: 08/02/07 11:37	

Completed by Radio:	Cancel:	Total Crew Hours: 0.25
---------------------	---------	------------------------

Referral: Priority:	Ref to Radio:	Work Code:	Fac Type:	Fac Seq #:
Job Desc:				

Last Update Dt: 08/02/07	Last Update ID: 1	Last Batch Update Dt:	Last Batch Update ID:
WO Completed Dt: 08/02/07	Completed By: LVE		

is is the last work order.

Start Sewer/Water L...

SR #

3001954

Creation Dt/Tm

08/02/07 16:06

Last Update Dt / ID

08/02/07 16:07 L7C

SR Comments

CON CLAIMS ST HAS STARTED TO LEAK AGAIN CLAIMS WHEN UNIT WENT OUT IT WAS DRY BUT IS LEAKING
AIN

Page 1 of 1

3001954

08/02/07 11:38

08/02/07 11:38

B4F

SR Comments

PAGED 1933....MF

Page 1 of 1

Exhibit 32

Sewer/Water Infrastructure Management

Actions



Work Order Data Entry

SR #: 3002160	Wor#: 1	Priority: 1	Radio #: 1933	Wtr/Swr: W	WO Stat: CMP	WO Recd Dt:	Orig Prob Cd: 1161
Prob Cd / Primary Ind: 1161 Y		Data Steward: 1970 MICHAEL BASOM				Field Bk Pg/Grd: C12S	
Street #	Frac	Dir	Street Name	Sfx	Suite#	Juris	Thomas Bros Pg: 1248A2
5715			SOLEDAD MTN	RD		SD	Service Area: 2
X St: DESERT VIEW DR							ES Service Area: W
Loc Desc: 1161 S							Plant Service Area: MI
Job Desc:							Assign Dt: 08/03/07 10:26
Special Inst:							WO Gen Dt: 08/03/07 10:21

USAF: Exp Dt: Fac Typ: WTRM Fac Seq#: 389251 Requestor: TOM PH#: 619 997-4359

Work Cd	Action Cd	Service Request Comments	
ESINV	REF11	ST: 08/03/07 11:30	End: 08/03/07 11:45 JO #: 53546 Emp: 1 Hrs: 0.30

WO Comments: Page 1 of 1 1161 FROM REPAIR PATCH - WORK ORDER 5 CANCELLED

Creation Dt/Tm: 8/6/07 13:33

Upd Dt/Tm: 8/6/07 13:34 LXR

Completed by Radio: Cancel: Total Crew Hours: 0.25

Referral	Priority	Ref to Radio	Work Code	Fac Type	Fac Seq #
Job Desc:					

Last Update Dt: 8/6/07 13:34 Last Update ID: LXR Last Batch Update Dt: 8/7/07 14:03 Last Batch Update ID: U97SRGCLN

WO Completed Dt: 8/6/07 13:53 Completed By: LXR

Please Wait.... Swim is currently sending this screen to your printer.

Sewer/Water Infrastructure Management

Actions



Work Order Data Entry

SR#: 3002160	Wo#: 2	Priority: 1	Radio #: 1972	Wtr/Swr: W	WO Stat: CMP	WO Recd Dt:	Orig Prob Cd: 1161
Prob Cd / Primary Ind: 1161 Y							Field Bk Pg/Grid: C12S
Street #	Frac	Dir	Street Name	Sfx	Suite#	Juris	Date Steward: 1630 JEFF REMSBURG
5715			SOLEDAD MTN	RD		SD	X St: DESERT VIEW DR
Inter:							
Loc Desc: 1161 S							
Job Desc:							
Special Inc:							
							Thomas Bros Pg: 1248A2
							Service Area: 2
							ES Service Area: W
							Plant Service Area: MI
							Assign Dt: 08/03/07 16:24
							WO Gen Dt: 08/03/07 10:35

USA:	Exp Dt:	Fac Typ: WTRM	Fac Seq#: 389251	Request: TOM	PH: 619 997-4359
------	---------	---------------	------------------	--------------	------------------

Work Cd	Action Cd	Service Request Comments			
RPR	RPR				
		ST: 08/06/07 08:00	End: 08/06/07 15:00	JO #: 53519	Emp: 5 Hrs: 7.00

WO Comments: Page 1 of 1	REPLACE STAINLESS BAND ON 12" AC RECONNECT SVC - WORK ORDER 6 REFERRED TO RADIO # 1930
Creation Dt/Tm: 8/7/07 10:49	
Upd Dt/ID: 8/7/07 10:49 FME	
Completed by Radio #:	Cancel:
Total Crew Hours: 35.00	

Referral Priority:	Ref to Radio:	Work Code:	Fac Type:	Fac Seq #:
Job Desc:				

Last Update Dt: 8/7/07 10:49	Last Update ID: FME	Last Batch Update Dt: 8/8/07 4:00	Last Batch Update ID: U9ZSRGEM
WO Completed Dt: 8/7/07 10:49	Completed By: FME		

Please Wait.... Swim is currently sending this screen to your printer.

SR #**Creation Dt/Tm****Last Update Dt / ID**

3002160

08/06/07 12:55

08/06/07 12:55 J9L

SR Comments

PER 1630 HE IS SENDING HIS OPERATOR TO HANDLE THIS CALL...JKL

Page 1 of 2

3002160

08/06/07 12:18

08/06/07 12:18 J9L

SR Comments

PER 1972 REQ STREET SWEEPER FOR 5700 BLOCK OF SOLEDAD MTN RD...PAGED 1801...JKL

Page 1 of 2

3002160

08/06/07 11:07

08/06/07 11:08 J9L

SR Comments

PER 1972 WATER 10-7 15MIN FOR REPAIRS ON 12"MAIN, REQ 7-96, TAKE FROM SPIGOT AFTER REPAIRS ON 12"MAIN..PAGED 1933..JKL

Page 1 of 2

3002160

08/03/07 10:36

08/03/07 10:37 KJW

SR Comments

PER 1933 RENEWED REPAIR IS LEAKING BADLY/SINKING...NEED TO FIX IT TODAY...1630 PGD...KEN/38

Page 1 of 2

Exhibit 33

Jim Fisher - Fwd: Re: Soledad Mtn Road

From: Alex Ruiz
To: Jim Fisher; Johnny Mitchell
Date: 8/6/2007 10:25 AM
Subject: Fwd: Re: Soledad Mtn Road

Jim: Not sure about the situation but it appears as though this is becoming a bigger issue.
Can you give me an update regarding the repairs?

Alex

(619) 533-6692
Assistant Director
Water Department

>>> Thyme Curtis 8/6/2007 9:58 AM >>>
Hello,

Tom Crab just called and said there are new cracks in Soledad Mtn Road, as of today, that seems to indicate a much larger problem and is worried that a major problem needs to be averted.

There are new cracks at 5725 Soledad Mtn. Road, and the ground is sinking. Mr. Crab said that there is a lot of water from the leak, and that crews are working on the leak right now, though the street is cracking very badly "as we speak" and SDG&E has vented the street to prevent an explosion, as there is a gas leak. He was very concerned, I told him I would immediately email his concerns to the proper people.

Thank you,

Thyme

Thyme Curtis
Council Representative
Councilmember Kevin Faulconer, Second District
(619) 236-7351 (phone)
(619) 236-6996 (fax)

Disclosure: This email is public information. Correspondence to and from this email address is recorded and may be viewed by third parties and the public upon request.

>>> Richard Haas 7/19/2007 11:26:42 AM >>>
Hi Thyme,

Jim Barrett, the Director of the Water Department, is researching this problem and is planning to call Mr. Crab back.

Jim or Alex Ruiz (Assistant Director) will send you an e-mail and let you know the summary of their discussions.

Rich

>>> Thyme Curtis 7/19/2007 10:34 AM >>>

Hi Rich,

A constituent named Tom Crab (619.997.4359, 5703 Soledad Mtn Road) just called and is very concerned about Soledad Mtn Road, specifically in front of 5715 Soledad Mtn Road. He said that the street has been sinking and cracking for the past few months, and back in March 2007 he reported a crack in the street that was subsequently patched. Last night a pipe cracked and is currently being fixed by city crews, but Mr. Crab believes something more is going on underneath the street, that it is sinking or moving. He's hoping a geologist or engineer can take a look before something major happens.

Thanks,

Thyme

Thyme Curtis
Council Representative
Councilmember Kevin Faulconer, Second District
(619) 236-7351 (phone)
(619) 236-6996 (fax)

Disclosure: This email is public information. Correspondence to and from this email address is recorded and may be viewed by third parties and the public upon request.

Exhibit 34

From: Alex Ruiz
To: Jim Barrett; Jim Fisher; Thyme Curtis
Date: Mon, Aug 6, 2007 2:18 PM
Subject: Fwd: Re: Soledad Mtn Road

All:

The following is a summary of today's observations from Jim Fisher, Water Ops Division Deputy Director, who personally visited the Soledad Mt Rd site this morning:

- A water leak reported on Friday was the result of a defective repair saddle. It appears that the adhesive used to attached the gasket to the stainless steel saddle failed and allowed water to leak out. - The actual amount of water coming from the previous repair/patch was minimal, so the leak was held until today for repairs.
- The cracks in the street do not appear to have changed since Operations Division managers visited the site a couple weeks ago.
- The report of "a lot of water" was the result of the main draining activity associate with the leak repairs and the excavated hole being pumped out. As mentioned before there was minimal leakage coming from the failed saddle itself.
- Our understanding was that SDG&E was on site to shutdown a gas service to a single residence who had a leak and that it was in no way related to the leaking water service.
- Johnny Mitchell, Acting Construction Manager spoke to Mr. Crab, who showed Johnny what he thought was additional ground subsidence and a crack on the house at this address (see attached pictures). Neither the subsidence or crack appear to be related to the blown service in mid July, nor the leak on Friday.

In conclusion, it does not appear that anything has changed in the area since the last time we were out there in mid July.

Staff will follow-up on the on-going analysis of the area in an effort to eliminate potential causes of street cracking. Staff will follow-up with MWWD to see what they have found in the televising of the sewer main, then with Field Engineering on boring the street to see if there is any undermining occuring.

If you have any questions, please let me or Jim Fisher know.

Alex

(619) 533-6692
Assistant Director
Water Department

>>> Thyme Curtis 8/6/2007 9:58 AM >>>
Hello,

Tom Crab just called and said there are new cracks in Soledad Mtn Road, as of today, that seems to indicate a much larger problem and is worried that a major problem needs to be averted.

There are new cracks at 5725 Soledad Mtn. Road, and the ground is sinking. Mr. Crab said that there is a lot of water from the leak, and that crews are working on the leak right now, though the street is cracking very badly "as we speak" and SDG&E has vented the street to prevent an explosion, as there is a gas leak. He was very concerned, I told him I would immediately email his concerns to the proper people.

Thank you,





